

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1164	318/430-434.ccls. and motor and current and phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/09 13:41
L2	138	318/430-434.ccls. and motor and current adj (limit or decrease or overheat) and phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/09 13:48
L3	6	("4451771" "5038092" "5140248" "6300741" "6838844" "6861813").PN. OR ("6992448").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/02/09 13:47
L4	271	318/700-800.ccls. and motor and current adj (limit or decrease or overheat) and phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/09 13:50
L5	171	318/254.ccls. and motor and current adj (limit or decrease or overheat) and phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/09 13:54
L6	6	("4451771" "5038092" "5140248" "6300741" "6838844" "6861813").PN. OR ("6992448").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/02/09 13:52
L7	92	318/138.ccls. and motor and current adj (limit or decrease or overheat) and phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/09 13:59
L8	87	318/439.ccls. and motor and current adj (limit or decrease or overheat) and phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/09 13:59
L9	20	318/809.ccls. and motor and current adj (limit or decrease or overheat) and phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/09 13:59

L10	49	318/811.ccls. and motor and current adj (limit or decrease or overheat) and phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/09 14:10
L11	140	takayuki near kifuku	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/09 14:21
L13	6	(drive and controller and integrating and motor and current and limit). CLM.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/02/09 14:22